

Identifier

FRS Incident Number: [REDACTED]

Incident status: Published

Recording FRS: Hampshire & Isle of Wight

Recording station: St Marys

Recording Fire Officer: [REDACTED]

'Over the border' incident: No

Call

Origin of call: Other

Incident type at call: Building

▶ Timings

Time of call: 21 September 2024 00:16:16

Late call: No

Date/time of stopped message: 21 September 2024 02:05:10

Date/time closed: 21 September 2024 05:08:48

Attendance

Incident category:	Fire
Type of property:	Building > Dwelling > Purpose Built Flat/Maisonette - multiple occupancy > 4 to 9 storeys
Property regulated:	Yes
Number of appliances deployed:	3
Victims involved:	No
Evacuation involved:	No
Attack on firefighters:	No
Derelict buildings involved:	No
Chimney fire:	No

► Location of incident

Building name:	LEDBURY HOUSE
Street:	JOHN THORNYCROFT ROAD
Town:	SOUTHAMPTON
Postcode:	SO19 9SY
Location description:	LEDBURY HOUSE,JOHN THORNYCROFT ROAD,SOUTHAMPTON,SO19 9SY
X-coordinate:	0443593
Y-coordinate:	0110815

Other Details

Multiple seats: No
Time between ignition and discovery: Not known
Time between discovery and call: Not known
How the fire was discovered: Person
Cause/motive: ████████████████████
Occupied at time of incident: Yes
Building normally occupied: Yes - occupied
State of building's means of escape: OK - no visible concerns
State of building's compartmentation found: Breached - fire doors left open or incorrectly fitted

▶ Alarm systems

Alarm System Type	Location	Operated	Reason for poor Outcome
Mains security system including smoke alarm	Different floor from fire	No	Fire in area not covered by system
Were hazardous materials involved:		No	

Resources

Number of non-rider officers: 3

▶ Vehicles

Type: Pumping - Water tender ladder

Time mobilised: 21 September 2024 00:19:35

Deployed from Home Station: Hampshire & Isle of Wight > [REDACTED]

Time mobile: 21 September 2024 00:21:02

Time at scene: 21 September 2024 00:33:06

Time available: 21 September 2024 02:28:39

Demounted resource: No

Number of crew: 1

FRS Callsign: [REDACTED]

Type: Pumping - Pump / Pump ladder

Time mobilised: 21 September 2024 00:19:35

Deployed from Home Station: Hampshire & Isle of Wight > [REDACTED]

Time mobile: 21 September 2024 00:19:45

Time at scene: 21 September 2024 00:29:20

Time available: 21 September 2024 04:54:31

Demounted resource: No

Number of crew: 1

FRS Callsign: [REDACTED]

Type: Pumping - Water tender

Time mobilised: 21 September 2024 00:19:36

Deployed from Home Station: Hampshire & Isle of Wight > [REDACTED]

Time mobile: 21 September 2024 00:20:42

Time at scene: 21 September 2024 00:33:00

Time available: 21 September 2024 02:12:20

Demounted resource: No

Number of crew: 1

FRS Callsign: [REDACTED]

▶ Equipment

Type	Number Used
Water Delivery - Hosereel - high pressure	1
RPE - CABA - standard duration	4

▶ Fire officers

RCC Callsign	FRS Callsign
	██████
	██████
	██████

Action

Delay in commencing firefighting action: No delay

Main action taken by the general public prior to arrival: None

Main action taken by FRS personnel: Hosereel (high pressure) (HRJ) - augmented supply

▶ Active safety systems

Type:	Smoke ventilation
Location in relation to fire:	On same floor as fire
System operated:	No
Impact on fire:	Not known
Reason system did not function as intended:	Fault in system

Damage - How the fire started

Main cause of fire:	[REDACTED]
Person or action that caused the fire:	[REDACTED]
Source of ignition:	Vehicles only - Engine, fuel line or pump
Powered the ignition:	Not applicable
Item that ignited first:	Explosives, gas, chemicals - Petrol/Oil products
Item mainly responsible for spreading fire:	Explosives, gas, chemicals - Petrol/Oil products
Rapid fire growth caused by:	Yes, petrol/oil products

Damage - Substances/explosions involved

Dangerous substances involved:	Flammable liquids
Explosion:	No

Damage - Property information

Type of room/compartment fire started in:	Garage
Household occupancy at time of incident:	Not known
Factors contributing to start of fire:	Not known
Impairment due to suspected drugs/alcohol:	Don't Know
Special method of building construction:	Not known
Heat and smoke damage only:	No
Size of fire when fire service arrived:	Limited to item 1st ignited
Distance from adjacent properties (m):	No other property affected
Distance from adjacent properties at stop (m):	No other property affected
Damage restricted to:	Limited to item 1st ignited
Extent of the fire damage at stop:	None
Extent of the total area damaged (sq. m at stop):	None
Approximate size of room/compartment of fire's origin(sq. m):	101 - 200
Approximate size of floor at fire's origin (sq. m):	101 - 200
Number of floors above ground:	0
Number of floors below ground:	1
Floor fire originated:	-1

Persons

Number of casualties:	0
Number of casualties aged 0 to 15:	0
Number of casualties aged 16 and over:	0

Notes

Information Type	Note
Summary	1 motorcycle 100 per cent by fire - [REDACTED] - ventilation system in underground car park did not work correctly. Smoke spread reported on residential floors away from scene of fire. TFS inspected site and logged a number of failures in the engineered systems for the building - full fire safety audit to follow. [REDACTED]