

From: [REDACTED]
To: [Control Management](#); [REDACTED]
Cc: [REDACTED]
Subject: High Rise PDA
Date: 27 September 2021 14:01:53
Attachments: [image001.png](#)
[image002.jpg](#)
[image003.jpg](#)
[image004.jpg](#)
[image005.jpg](#)
[image006.jpg](#)

Dear Control,

The following addresses have had their evacuation strategies changed to Simultaneous evacuation and waking watch has been implemented due to the cladding and insulation on the building, can you please update the PDA accordingly:

29 to 36 Carpathia Drive, Southampton, SO14 3GU – CFRMIS - 10729039

37 to 55 Carpathia Drive, Southampton, SO14 3GU – CFRMIS - 10729045

56 to 67 Carpathia Drive, Southampton, SO14 3GU – CFRMIS - 10729128

Nev, can you please make sure that the SSRI is updated to show that the building has deficiencies in the External Wall System. I would also recommend a 72d by all crews.

Regards,

[REDACTED]



[REDACTED]

[REDACTED]

High Risk Residential Building Inspection Program

[REDACTED]

[REDACTED]



Headquarters
Leigh Road, Eastleigh
Hampshire, SO50 9SJ
02380644000