



Hampshire & Isle of Wight

FIRE & RESCUE SERVICE

Fire Regulations (England) 2022 - Fault Report

Reference number

20240507-001

Premises Details

Name of building	6 Portsmouth road
Address of building	Portsmouth Road 6 Cosham Portsmouth
Postcode of building	PO6 2AE
Name of responsible person	[REDACTED]
Phone for RP	[REDACTED]
Email for RP	[REDACTED] vividhomes.co.uk

Fault Details

Type of equipment	Lifts for use by firefighters or evacuation lifts
Type of lift to which the fault relates	Lift for use by firefighters
Nature of the fault	lift not responding
Location of the fault and / or area affected	affects whole building
Timescale for repair	unknown - awaiting engineer

Fault Mitigation

Has the fault necessitated a temporary change in evacuation strategy from stay put to simultaneous?	No
Have any additional measures been implemented to mitigate against the faults reported?	No
If yes, provide details	

Person completing the report

Name of reporter	[REDACTED]
Phone for reporter	[REDACTED]
Email for reporter	[REDACTED] vividhomes.co.uk
Date and time of report	07/05/2024 08:52